

October 6, 2010

Mr. Paul Cho, PG, Site Cleanup Unit IV
 California Environmental Protection Agency
 California Regional Water Quality Control Board, Los Angeles Region
 320 W. 4th Street, Suite 200
 Los Angeles, California 90013

**Re: Remedial System Monthly Summary Report for September 2010
 DFSP Norwalk Facility, Norwalk**

Dear Mr. Cho:

Parsons is transmitting the remedial system monthly summary report for September 2010 for the DFSP Norwalk Facility in Norwalk, California. This report will summarize remedial system operation for the month and include description of down time and individual well statistics.

| Groundwater Treatment System | | | | | | September 2010 | | |
|--------------------------------------------------------|-------------------------------------------------------|------------|--------------|------------|--------------|----------------|----------------------------------------|------------|
| Well ID | Flow Meter Readings | | | | | | Processed Discharge Total ¹ | |
| | GW-2/GW-13 | | GW-15 | | GW-16 | | Volume (gal) | Flow (gpm) |
| Date/Time | Volume (gal) | Flow (gpm) | Volume (gal) | Flow (gpm) | Volume (gal) | Flow (gpm) | Volume (gal) | Flow (gpm) |
| System down between 9/1/2010 and 9/7/2010 ² | | | | | | | | |
| 9/7/2010 8:20 ³ | 5499209 | 9.5 | 2444090 | 5.5 | 872567.0 | 2.7 | --- | NR |
| 9/9/10 12:25 | 5527758 | 9.5 | 2461100 | 6 | 880578.0 | 2.7 | 50907555 | 35 |
| 9/13/10 10:00 | 5580049 | 9.5 | 2461100 | 6 | 894904.0 | 2.5 | 50997800 | 22 |
| 9/15/10 11:45 | 5607953 | 9.5 | 2506105 | 5 | 902589.0 | 2.5 | 51044825 | 25 |
| 9/21/10 17:49 | 5660781 | 9 | 2537348 | 5.5 | 918387.0 | 2.5 | 51140120 | 36 |
| 9/24/10 10:15 | 5696628 | 9 | 2557991 | 5.5 | 928991.0 | 2.9 | 51206565 | 35 |
| 9/24/2010 12:54 | System shutdown for quarterly groundwater monitoring. | | | | | | | |
| Total Volume (Gal) Removed from Well | 198,456 | | 114,232 | | 56,522 | | 351,150 | |

- Total groundwater Discharge processed under NPDES permit no. CAG994004 CI-7585
- System remained down for repairs at wells GW-15 and GW-16. Also down for selenium exceedance observed on July 19th, awaiting confirmation sample results.
- GW-15 pump repaired and GW-16 pump replaced. Selenium samples (in triplicate) confirm that selenium exceedance is a laboratory anomaly. System restarted with accelerated selenium sampling (weekly) per permit requirement.

Vapor Extraction System

September 2010

System redesign in progress. System not in operation during this reporting period.

If you have any questions, please call me at 602-734-1083 or Mary Lucas at 626-440-6032.

Sincerely,

PARSONS



Redwan Hassan, PG
Project Manager

Distribution:

Mr. Kola Olowu, DESC-FQ
Mr. Tim Whyte, URS
Ms. Adriana Figueroa, City of Norwalk
Mr. Thomas Lynch, City of Norwalk
Mr. Norman Dupont, City of Norwalk Attorney
Mr. Charles Emig, City of Cerritos
Ms. Nancy Matsumoto, Water Replenishment District of So. CA
Mr. Mark Wuttig, CH2M Hill
Mr. Steve Defibaugh, KMEP
Ms. Mary Lucas, Parsons
Office of Congresswoman Grace Napolitano

RAB Members:

Ms. Mary Jane McIntosh
Dr. Eugene Garcia
Mr. Bob Hoskins
Ms. Tracy Winkler

