DFSP NORWALK PIPELINE RELEASES

NEW DISCOVERY

- April 15, 1999
- North of Truck Fill Stands, between Water Tank and FSII Tank
- 2 6 inch product pipelines
- Weathered JP-5?
- JP-5?
- Gravity flow
- Not indicated on facility drawings

EMERGENCY ACTION

- Soil excavated
- Pipelines cut back
- Both pipelines drained of product via vacuum truck
- Pipelines secured w/caps (welded)
- Federal and State notifications


IMMEDIATE ACTION

- Sample/test soil
- Remove and dispose soil (haul away)
- Line area w/plastic sheathing
- Backfill w/clean soil
- Compact to 90% density
- Install 4 inch aggregate top layer


FUTURE ACTION

- Develop workplan for remediation
- Remediate area


Map of Current Remediation Systems



Excavated Area Diagram



Map of Site and Excavated Area



CENTRAL PLUME REMEDIATION SYSTEM UPDATE

- Total Hydrocarbons Recovered to Date: 97,529 Gallons
- Liquid-Phase Hydrocarbons Recovered:
 50,509 Gallons
- Vapor-Phase Hydrocarbons Removed: 47,020 Gallons
- Dissolved-Phase Hydrocarbons Removed:
 540 Gallons

DESC Hydrocarbon Recovery

